	Туре	Ref #	Hits	Search Text
1	BRS	S7	242	S3 and substrates
2	IS&R	S2	1	("20020078741").PN.
3	BRS	S6	רו	S4 and (oxidation corro\$4) same protect\$3
4	BRS	S8	/	S7 and (oxidation corro\$4) same protect\$3
5	BRS	S3	1267	SAW and pressure adj sensor
6	BRS	S11	28	S10 and (substrates layers)
7	BRS	S10	1	S3 and (oxidation corro\$4) same protect\$3
8	BRS	S9	7	S7 and protect\$3 with seal
9	BRS	S5	16	S4 and (oxidation corro\$4)
10	BRS	S4	45	S3 and sens\$3 adj substrate
11	IS&R	S1	1	("4295102").PN.

	DBs	Time Stamp	Comments	Error Definition
1	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	1		
2	US-PGPUB; USPAT	2007/06/05 13:58		
3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	1		
4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	1		
5	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB			
6	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB			
7	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB			
8	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB			
9	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	l ' ' '		
10	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/06/05 14:18		
11	USPAT	2007/06/05 13:56		

	Errors
1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	